



Certificate of Registration

QUALITY MANAGEMENT SYSTEM - ISO/TS 16949:2009

This is to certify that:

HellermannTyton
6701 Good Hope Road
Milwaukee
Wisconsin
53223
USA

Holds Certificate No:

TS 593329-000

and operates a Quality Management System which complies with the requirements of ISO/TS 16949:2009 for the following scope:

The design and manufacture of cable care management products (molded fasteners and cable ties), network cabling products, wiring duct, raceway, assembly of pneumatic tools and identification systems products.



For and on behalf of BSI:

VP Regulatory Affairs, BSI Group America Inc.

Originally registered: 07/09/2013

Latest Issue: 07/09/2013

Expiry Date: 07/08/2016

IATF Number:

0166298



Page: 1 of 2

...making excellence a habit.™

Certificate No: **TS 593329-000**

Location

HellermannTyton
6701 Good Hope Road
Milwaukee
Wisconsin
53223
USA

Registered Activities

The design and manufacture of cable care management products (molded fasteners and cable ties), network cabling products, wiring duct, raceway, assembly of pneumatic tools and identification systems products.

Including the following support activities:

HellermannTyton
7930 Faulkner Road
Milwaukee, Wisconsin
Sales, Marketing, Design, Program Management, Tooling, QA (Pre-Production Lab (PPAP), Dimensional (CMM & Optical)).

HellermannTyton
Distribution Center
Bolingbrook, Illinois
Shipping & Warehousing.

HellermannTyton
8475 N 87th Street
Milwaukee, Wisconsin
Purchasing.



Originally registered: 07/09/2013

Latest Issue: 07/09/2013

Expiry Date: 07/08/2016

IATF Number: 0166298

Page: 2 of 2

This certificate remains the property of BSI and shall be returned immediately upon request.

An electronic certificate can be authenticated [online](http://www.bsigroup.com/ClientDirectory). Printed copies can be validated at www.bsigroup.com/ClientDirectory

To be read in conjunction with the scope above or the attached appendix.

Further clarifications regarding the scope of this certificate and the applicability of ISO/TS16949 requirements may be obtained by consulting the organization.